

### Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Clien	:: Stratus Initials: JDM Date: 7/6/17	Time: 18	-20	MST/MDT
	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?			
2	Were samples on ice or in a refrigerated state upon retrieval?			
	Courier Initials Date: 7:617 Time: 18:20			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?			
4	Chain of Custody (COC) present?	/		
5	Sample bottles intact? *			
6	Samples on blue-ice?		/	]
7	Samples on wet ice?	/		
8	Samples received within 4 hours of sampling?			]
9	Record temperature of sample bottles within cooler with infra-red  Container #	thermomete	r.	
	Temp °C \7.6	V		
	Application of the Control of the Co	Yes	No	NA
10	Sample thawed and free of any ice? *			
11	COC complete, legible, signed and dated?			-
12	Labels on bottles complete and legible? *			=
13	COC in agreement with sample bottle labels? *			-
14	Proper container used for analyses requested? *			
15	Samples requiring preservation preserved correctly? *			
16	Sufficient sample volume for analyses requested? *			
17	Samples within holding times for analyses requested? *	/		
18	Samples requiring no headspace are free of headspace? *  (VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	<pre>green pe</pre>	a,	> green pea
	* If no, document on Chain of Custody.			
Notes				



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Batch 2456642

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEGUSEONLY G Z G G VO	CLIENT:			ratus Compan	ies - Ste	wart	Labs			Name: SAMPLER
	SAMPLE	COLLECTION Time	Grab / Comp	CLIENT SAMPLE I	DENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED
11325	7.10.17	2:45	GI	M W- 1		LN N	7	5	Method 8260 (see back of COC) - SL	
										Metals - (see back of COC) SL
										Inorganic Analysis (see back of COC) - SL
check. Yes,	es may require record and rep	you to report the	e tempera	ture of samples as they ar No, temperature not reque	rive in the labor sted.	ratory. W	ould you	like the ten	nperature	of samples recorded upon receipt by the laboratory? Please
Leaving this field I	olank implies t	that the incomi	ng tempe	rature is not requested.						
RELINQUISHED BY		DATE / TIME	Received	l by	Date / Time	RECUES	STED CO	MPLETION	DATE	REPORT TO: PHONE:
XIIII	8 1	19:00	pt	mille	10:00					FAX:
Relinquished by		Date / Time	Réceived				WW = wa	IX TYPE		ADDRESS:
Relinquished by	Date / Time   Received by   D			Date / Time	S=	L = Liquid soil	nking wate d SL =	2 CH 54	CITY, STATE ZIP:	
,		Date / Time Received by			A = Air SD = Solid  CDPHE REPORT REQUIRED			Solid **	INVOICE TO:	
Database Entry By		Date					PWSID # ADDRESS:			
		17	Sar	Sample Kit Sent? Yes / No CITY, STATE ZIP:			CITY, STATE ZIP:			



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Batch: 9115 5 9 372

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs			Name: SAM	PLER Sterxit	
Striple No. St. 72 TO L	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES	REQUESTED	
	7-12-17	17:00	61	M W-1						Mathad 9260 (egg back	COCK-SI	
										Metale (cash others)	1967.61	
										Inorgania Analysia (as		
									1	COD		
		4.00										
check. Yes,	record and rep	ort temperature	)	No, temperature not reque	ested.		rouia you	like the ten	nperature	of samples recorded upon rece	ept by the laboratory? Please	
	A			rature is not requested.			100					
RELINQUISHED BY	XX	DATE / TIME	Received	Py 11	Date / Time 7/13/17	REQUE	STED CO	MPLETION	DATE	REPORT TO:	PHONE:	
$\mathcal{Q}_{-}$		19:00	ptot	n while	10:00					CLIENT:	FAX:	
Relinquished by		Date / Time	Réceived	ру	Date / Time		WW = wa	IX TYPE		ADDRESS:		
Relinquished by	Date / Time   Received by Date / Time				Date / Time	S:	L = Liquid soil	nking wate		CITY, STATE ZIP:		
,					20,07 11110	S = soil SL = sludge A = Air SD = Solid CDPHE REPORT REQUIRED			Solid	INVOICE TO:		
Database Entry By	37.1111 Date						PWSID#			ADDRESS:		
	Date 7/13/17						Sample Kit Sent? Yes / No CITY, STA			CITY, STATE ZIP:	IY, STATE ZIP:	



Edeir

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: ( PAGE \_\_\_\_ OF \_\_\_\_

- MUS (0.1)	CLIENT:		S	tratus	Compan	ies - A0	z			Name: 🔾	ance Stewart
Sample No.	SAMPLE	COLLECTIO	N INFO	voi i i				QC	Total Na	Signature:	4
	Date	Time	Grab / Comp	CLIENT S	SAMPLE IDENT	TIFICATION .	Matrix Type	Report Neede	Total No. of Cont.	C	ANALYSES REQUESTED
ILLIE CONTRACTOR	7.12.17	12:00	GI	ML	7 - 1		とと		4		270 (see back of COC) - ACZ
			•			1 4		1	3	1	HALL STATE OF THE CANAL PROPERTY.
										Total Org	ganic Carbon - ACZ
							e laborat	tory. Wo	uld you like	the tempera	ture of samples recorded upon receipt by the
RELINQUISH			Received by		Date / Time	eo. Elouestei	COMP	PETION	DATE	REPORT TO:	41.00
7-6		7.12.17		DER	7.12.17						PHONE:
0	- 01	11.21	NUS	0011							FAX:
		10. 2	10 7	er 180	16.30				N.	CLIENT:	
Relinquished	by	Date / Time	Received by		Date / Time		MATRIX		Very)	1000000	
								waste wa rinking w	The state of the s	ADDRESS:	
						DW = drinking water  L= Liquid				CITY, STATE Z	IP:
Relinquished by Date / Time Received by Date / Time					Date / Time	S = so	الد	SL:	= sludge		
~4969409409296			C-Nortestations	HINDSHEE STAN		S = soil SL = sludge A = Air SD = Soild			= Solid	ADDRESS:	
Database En	ttry:By		Dete			PWSID #					
						Sample Kit Sent? Yes / No				CITY, STATE Z	IP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compan		Name: Janes Stewart					
Sample No. S16-252	SAMPLE Date	Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED	
112F	7.20.17	14:00	G	MW-1			WW	4		Method 8280 (see back of COC) - SL	
										Metals - (see back of COC) 3L	
				-					_ 1	Inorganic Analysis (see back of COC) - SL	
								1.	授	Sulfide	
									1	Cv	
Compliance sample	es may require	you to report th	e tempera	ture of samples as they an	rive in the labor	ratory. W	ould you	like the ten	nperature	of samples recorded upon receipt by the laboratory? Please	
	Sept 10 Mag		The state of the state of	rature is not requested.							
RELINQUISHED BY	4	DATE/TIME	Received	by /	Date / Time	REQUE	STED CO	MPLETION	DATE	REPORT TO: PHONE:	
Jack C	1-1	7.20.17	both	derfle	7/21/17					FAX:	
Relinquished by		Date / Time	Received	by	Date / Time			IX TYPE			
								aste water nking wate	r	ADDRESS:	
Relinquished by		Date / Time	Received	by	Date / Time			SL=	sludge	CITY, STATE ZIP:	
						A = Air SD = Solid CDPHE REPORT REQUIRED				INVOICE TO:	
Database Entry sy			PWSID#								
		D N		7/21/1		Sample Kit Sent? Yes / No			/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Satch:
--------

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compai	nies - Ste	wart La	bs			Name: James SAMPLER STEWART	
Spriple No Cy 13 L 14 C	SAMPLE Date	COLLECTION Time	Grab / Comp	CLIENT SAMPLE	IDENTIFICATION			QC Report leeded	Total No. of Cont.	Signature: NALYSES REQUESTED	
re e	711717	15:00	G	MW. 27	2	W	Ŋ		7	Method 8260 (see back of COC) - SL	
										Metals - (see back of COC) SL	
										Inorganic Analysis (see back of COC) - SL	
										Sulfide	
										Cn	
				iture of samples as they No, temperature not requ		ratory. Would		e the tem	perature	of samples recorded upon receipt by the laboratory? Please	
		that the incom	ing tempe	rature is not requested							
RELINQUISHED BY	7000 (	7.17.17	Received	by	Date / Time 7   18   17	REQUESTE	COMP	PLETION	DATE	REPORT TO: PHONE:	
	19:00 Lyh 10/10 11								Barane and a	FAX:	
Relinquished by	Date / Time Received by Date / Ti						/ATRIX	e water		ADDRESS:	
	y Date / Time Received by Date / Time					DW = drinking water L = Liquid			1443	CITY, STATE ZIP:	
Relinquished by		Date / Time	received	бу	Date / Time	S = soil A = Air	SD =		INVOICE TO:		
Database Entry By							CDPHE REPORT REQUIRED PWSID #			ADDRESS:	
	Ų	M	70.0	7/18/17		Sample Kit Sent? Yes / No CITY, STATE ZIP:			CITY, STATE ZIP:		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500

-				
-2	COL	mi	0.	
ıa	COL	2 5 1 4	U.	

EC USE ONL Client No.	CLIENT:			Stratus	s Comp	anies -	ACZ			Name:	anes Starat
Sample No.	SAMPLE	COLLECTIO	ON INFO							Signature:	1-8
S ()	Date	Time	Grab / Comp	CLIENT SA	MPLE IDEN	TIFICATION Matrix QC Report Total No. of Needed Cont.			. ,		ANALYSES REQUESTED
	7.17.17	15-00	G	MW.	7.R		NW		3	Phenols	
			7							Total Orga	anic Carbon
										Method 8270 (	all normal compounds, including those below)
										Benzyl B	utyl Phthalate
										Bis(2-eth	ylhexyl) phthalate
										Di-n-buty	l Phthalate
										Diethyl P	hthalate
										Dimethyl	Phthalate
										Di-n-octy	l Phthalate
				4						1,4-Dioxa	
										Benzoic /	
										Bencyl al	
					Min.					2-Methylp	
Compliance	samples may	require you t	o report the te	mperature of	samples as th	ey arrive in th	e laborator	y. Would yo	u like the tem	perature of s	amples recorded upon receipt by the
Leaving this	s field blank i	mplies that t	he incoming t	emperature i	s not reques	ted.				ASS.	
RELINQUISH	The second second		Received by	W. Carlotte Co. Carlotte Co.		REGGEOTE				REPORT TO:	PHONE:
-fun	VX.	laria d	CTF.	1/14/10	1430						FAX:
	,	714:80	41 1	1.11						CLIENT:	
Reiinquished	by	Date / Time	Received by		Date / Time	The Second Second	MATR	IX TYPE			
							DW = drir	iste water iking water		ADDRESS:	
Relinguished	hu	D-4- / Ti	Received by		D-4- / Ti		L = Liquid	01 -		CITY, STATE Z	IP:
Reinquisneu	БУ	Date / Time	Received by		Date / Time	A = Air SD = Solid			= Solid	INVOICE TO:	
						GDPHEREPORT REQUIRED					
Database En	try By		Date			PWSID#				ADDRESS:	
						Sa Sa	mple Kit S	ent? Yes /	No Messa	CITY, STATE Z	IP:



# Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Client	: Stratus Initials: JDM Date: 7/18/17	Гіте: <u>//</u>	00_	MST/MDT								
	To be filled out by laboratory courier, if applicable:	Yes	No	NA								
1	Were samples retrieved by a laboratory courier?	/										
2	Were samples on ice or in a refrigerated state upon retrieval?	/		2								
	Courier Initials: 12 Date: 7-17-17 Time: 19:00											
	To be filled out by laboratory sample receiving:											
3	Shipping container/cooler intact?											
4	A DESCRIPTION OF THE PROPERTY											
5	Chain of Custody (COC) present?  Sample bottles intact? *											
6	Samples on blue-ice?											
7	Samples on wet ice?	1										
8	Samples received within 4 hours of sampling?											
	LO COMPAN SERVICIONES PROPERTO A SERVICIO SERVICIO DE LA COMPANSA CONTRACTOR											
9	Record temperature of sample bottles within cooler with infra-red t	hermomete	r.									
	Container #											
	Temp °C 43. 9.4											
		Yes	No	NA								
10	Sample thawed and free of any ice? *											
11	COC complete, legible, signed and dated?											
12	Labels on bottles complete and legible? *			,								
13	COC in agreement with sample bottle labels? *											
14	Proper container used for analyses requested? *											
15	Samples requiring preservation preserved correctly? *											
16	Sufficient sample volume for analyses requested? *											
17	Samples within holding times for analyses requested? *											
18	Samples requiring no headspace are free of headspace? *											
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	<pre>green pe</pre>	ea,	> green pea								
	* If no, document on Chain of Custody.											
 Notes:	Sangles claced in frije up	on be	eins									
	droced off		J									



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Bate 1:721 5 6 7/2 7

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEAUSE (NE)	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs			Name: James Stervart
Sample No. S1 0- 202	SAMPLE (	COLLECTION	Grab / Comp	CLIENT SAMPLE I	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED
	7.20.17	15:30	GI	MW-Z	R		ww	4		Method 8200 (see back of COC) - SL
			,							Metals - (see back of COC) SL
										Inerganic Analysis (see back of COC) - SL
									1	Sulfide
Compliance sample checkYes	es may require , record and rep	you to report the port temperature	e tempera	iture of samples as they ar No, temperature not reque trature is not requested.	rive in the labor ested.	ratory. V	ould you	like the ten	nperature	of samples recorded upon receipt by the laboratory? Please
	blank implies t								3.44	
RELINQUISHED BY		7.20-17	Received	1 A A	7/21/17				16/A ( 6	REPORT TO: PHONE: FAX:
Relinguished by	, ,	/9:00 Date / Time	Received	ah offe	11:30 Date / Time		WATE	IX TYPE		CLIENT:
interinquisited by		Date / Tille	, caperveo		Date / Tille	MAN COL	WW = ws	ste water		ADDRESS:
Relinquished by		Date / Time	Received	by	Date / Time	S:	L = Liquid = soil	i → SL =	sludge	CITY, STATE ZIP:
							DW = drinking water L = Liquid +  E S = soil SL = sludge A = Air SD = Solid  COPME REPORT REQUIRED			INVOICE TO:
			Date	7/2///7		State of the state	And the state of t		The Contract of the Contract o	ADDRESS:   CITY, STATE ZIP:
						Sai	mple Kit S	ent? Yes	/ No ***	OTT, OTALE ZIF.



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compan	ies - Ste					Name: James SAMPLER	Sart
Simple No S1 <b>6</b> - 19 2	SAMPLE Date	COLLECTION	Grab / Comp	CLIENT SAMPLE I	DENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES REQUE	ESTED
II GA	7.10.17	10:50	GI	MW-3			WN 1/5		3	Method 8260 (see back of COC) - SL	
			,						Metals - (see back of COC)	SL	
									Inorganic Analysis (see bac	k of COC) - SL	
					*,						
Compliance sample check. Yes	es may require record and rep	you to report the ort temperature	e tempera	ture of samples as they ar No, temperature not reque	rive in the labo sted.		ould you l		nperature	of samples recorded upon receipt by t	the laboratory? Please
				rature is not requested.							
RELINQUISHED B		2-1017	Received	7 10.	Date / Time 7/11/17	REQUES	STED CO	MPLETION	DATE	REPORT TO:	
	9	19:00	yses	refle	10:00					CLIENT:	
Relinquished by		Date / Time	Réceived	by	Date / Time	Variation	WW = wa	IX TYPE		ADDRESS:	
Polinewio and have		Data (T)	Dooders	h	D-1-/		L = Liquid	nking wate	* 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	CITY, STATE ZIP:	
Relinquished by		Date / Time	Received	ы	Date / Time			SL = SD =		INVOICE TO:	
Database Entry By			Date	and the second s		CDPHE REPORT REQUIRED  PWSID #				ADDRESS:	
		JDM	Date	7/12/17		Sar	Sample Kit Sent? Yes / No CITY, STATE ZIP:				



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Sate		
bababaad		

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart L	.abs			Name: James Stewart	
57 <u>2</u> 89	SAMPLE (	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	JNI I	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED	
1766	7.17.17	14:00	61	MW-3		U	ンと		١	Method 8260 (see back of COC) SL	
			-							Metals - (see back of COC)-SL	
										Inorganic Analysis (see back of COC)—SL	
										Sulfide~	
										Cn	
					··· <del>·</del>						
Compliance sample	es may require	you to report th	e tempera	ture of samples as they a No, temperature not reque	rrive in the labor	ratory. Wou	uld you l	ike the ten	perature	of samples recorded upon receipt by the laboratory? Please	
Leaving this field I	olank implies t	hat the incom	ing tempe	rature is not requested.							
RELINQUISHED BY	1	DATE / TIME 7 - 17 - 17			Date / Time 7/18/17	RECUEST	ED CO	<b>VPLETION</b>	DATE	REPORT TO: PHONE:	
A.	101	19:00	1/2	chille.	11:00					FAX:	
Relinquished by						W		X TYPE		ADDRESS:	
						D	W = drir	nking water		CITY, STATE ZIP:	
Relinquished by		Date / Time Received by Date / Time				S = s A = A	oil Air	SL = : SD =	sludge Solid	INVOICE TO:	
Database Entry By			Part of the second					OR) REQUI	COURSE OF THE PERSON NAMED IN	ADDRESS:	
Padbase Listy by	Ú	DAM.	Date	7/18/17		Samp	le Kit Se	ent? Yes	/ No	CITY, STATE ZIP:	



Batch-

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525 Telephone: (970) 226-5500

	CLIENT:			Stratus Compa	anies -	ACZ	Name: Jaules Stewart		
Sample No.	SAMPLE	COLLECTIO	ON INFO	. 10					Signature:
	Date	Time	Grab / Comp	CLIENT SAMPLE IDENT	TIFICATION	Matrix Type	Needed	Total No. of Cont.	ANALYSES REQUESTED
									Phenois
	7.17.17	14:00		MW-3		NN		1	Total Organic Carbon
									Method 8270 (all normal compounds, including those below)
									Benzyl Rutyl Phthalate
									Bis(2-eth)(hexyl) phthalate
									Di-n-butyl Phthalate
								:	Diethyl Phthalate
									Dimethyl Phtha(ate
									Di-n-octyl Phthalate
									1,4-Djóxane
									Benzoic Acid
									Bencyl alcohol
									2-Methylphenol
Compliance s	samples may	require you t	o report the te	mperature of samples as the	ey arrive in th	e laborato	y. Would yo	ou like the tem	perature of samples recorded upon receipt by the
Leaving this	field blank i	pplies that the	he incoming	emperature is not request	ed.				
RELINQUISH	ED B	DATE / TIME	Received by	Date / Time	REQUESTE	D GOMHIA	TION DATE		REPORT TO: PHONE:
	•	14:30	1/19/	17 1000					FAX:
Relinguished b	hu.		Received by	1430			N/ EVDE		CLIENT:
rtelinquisned i	Бу	Date / Time	Received by	Date / Time	MATRIX TYPE  WW = waste water			Swin-su Adameter C	ADDRESS:
					DW = drinking water				
Relinguished to	bv	Date / Time	Received by	Date / Time	L = Liquid : S = soil SL = sludge			sludge	CITY, STATE ZIP:
	,	Date / Time	,	Jake, Time	S = soil SL = sludge A = Air SD = Solid COPPLE REPORT REQUIRED			= Solid	INVOICE TO:
					OBT THE REL ON THE GOINED			ED	ADDRESS:
Database Entr	гу Ву		Dete		PWSID#			4-5-5	
					Samuel Sa	mple Kit S	ent? Yes /	No	CITY, STATE ZIP:

# X

#### CHAIN OF CUSTODY RECORD

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs			Namer Lives Stewart	
Sample No S10-209	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED	
1632	7.27-17	17:00	61	MW-4			WW	4	3	Method 8260 (see back of COC) - SL	
				,					1	Metals - (see back of COC) SL	
									1	Inorganic Analysis (see back of COC) - SL	
									1	Sulfide	
									(	Cn	
	# <u>.</u>										
					,						
				ture of samples as they an No, temperature not reque		ratory. W	ould you	like the ten	perature	of samples recorded upon receipt by the laboratory? Please	
				rature is not requested.							
RELINQUISHED BY		1.27.17	Regalved	by	Date / Time 7/27/17	REQUES	STED CO	MPLETION	DATE	REPORT TO: PHONE:	
	0 1	16.20	St	happe	16:20					CLIENT:	
Relinquished by		Date / Time	Received	by	Date / Time		WW = wa	IX TYPE		ADDRESS:	
Belinguished by		Date / Time   Received by   Date / Ti					L = Liquid			CITY, STATE ZIP:	
Relinquished by		Date / Time	Received by Date / Time			A =	soil Air OPHE REPO	SD = SD = ORT REQUI	sludge Solid RED	INVOICE TO:	
Database Entry By			Date			PWSID		100		ADDRESS:	
, , , , , , , , , , , , , , , , , , , ,		)DM	-a.c	7/28/1	7	San	nple Kit S	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

	and the	Delta della	h	

Telephone: (970) 226-5500

Facsimile: (

EC USE ONL Client No	CLIENT:			Stratus Companies - ACZ							and S Stewart
	SAMPLE Date	Time	ON INFO Grab / Comp	CLIENT SA	MPLE IDEN	TIFICATION	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:	ANALYSES REQUESTED
	7-27-17	12:00	61	MW	-4		とと	-/	3		anic Carbon (all normal compounds, including those below)
										Benzyl Bu Bis(2-eth	utyl Phthalate yihexyl) phthalate
										Diethyl Pl Dimethyl	hthalate Phthalate
										1,4-Dioxa Benzoic	
									The second secon	Bencyl al	phenol
Leaving this	field blank i	mplies that t	he incoming t	emperature i	s not reques	ted.	304 30 Years			perature of sa	amples recorded upon receipt by the
10		7.2717	Received by	1/2/17						CLIENT:	PHONE:  FAX:
Relinquished	by	Date / Time	Received by		Date / Time	* 34 to **	WW = wa DW = drin	X TYPE ste water king water		ADDRESS:	IP:
Relinquished	by	Date / Time	Received by		Date / Time	WW = waste water DW = drinking water L = Liquid S = soil SL = sludge A = Air SD = Solid GDPHE REPORT REQUIRED			sludge = Solid = D	INVOICE TO:	
Dajabase ≘n	iry By		Date			PWSID#		ent? Yes /	No	CITY, STATE ZI	IP:



# Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Client	:: Stratus Initials: JDM Date: 7/27/17	Гіте: <u>/6</u>	:20	MST/MDT
	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?			
2	Were samples on ice ρr in a refrigerated state upon retrieval?	/		
	Courier Initials: 1 Date: 1.27.17 Time: 16.20			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?			
4	Chain of Custody (COC) present?			
5	Sample bottles intact? *			
6	Samples on blue-ice?		/	
7	Samples on wet ice?			
-8	Samples received within 4 hours of sampling?			
9	Record temperature of sample bottles within cooler with infra-red t	hermomete	er.	
	Container#			
	Temp °C 6.10			
		Yes	No	NA
10	Sample thawed and free of any ice? *			
11	COC complete, legible, signed and dated?			
12	Labels on bottles complete and legible? *			
13	COC in agreement with sample bottle labels? *			
14	Proper container used for analyses requested? *			
15	Samples requiring preservation preserved correctly? *			
16	Sufficient sample volume for analyses requested? *			
17	Samples within holding times for analyses requested? *			
18	Samples requiring no headspace are free of headspace? *			
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	<pre>green pe</pre>	ea,	> green pea
	* If no, document on Chain of Custody.			
Notes:	Put into fridge your ariuc			
	7 ,	<del>.</del>		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Balch 2 G (1/2

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SECUSE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart I	_abs			Name: James SAMP	Stewast
Sample No S10- 04	SAMPLE (	COLLECTION	INFO Grab / Comp	CLIENT SAMPLE	DENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES R	EQUESTED
	7.17:17	14:20	G	MW-,5		,	こと		6	Method 8260 (see back	of COC) - SL
									5	Metals - (see back of Co	DC) SL
										Inorganic Analysis (see	back of COC) - SL
										200	
				*							
Compliance sample	es may require	you to report th	e tempera	ture of samples as they ar	rive in the labo	ratory. Wo	uld you l	like the ten	perature	of samples recorded upon recei	pt by the laboratory? Please
	* 0.0	the same of the same	197 min	No, temperature not reque rature is not requested.	Sted.						
RELINQUISHED BY		DATE/TIME Y-12-17	Regelived		Date / Time	REQUES	ED CO	MPLETION	DATE	REPORT TO:	PHONE:
1	80	19:00	11	Sulli	7/13/17					CLIENT:	FAX:
Relinquished by		Date / Time	Received	by	Date / Time			IX TYPE			
							NV = dri	aste water nking wate	r	ADDRESS:	
Relinquished by		Date / Time	Date / Time Received by			S = A =		3L -	sludge Solid	CITY, STATE ZIP:	
			CD	PHE REPO	ORT REQUI	RED	ADDRESS:				
		N. W.	Date	37/27		PWSID	Davids	T.	<u> </u>		
	V	1914		7/12/	17	Sam	ple Kit S	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch (44) 5 674 7

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compan	ies - Ste	wart	Labs			Name: James SAMPLER SAMPLER	
Sample No. \$10-202_	SAMPLE Date	Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED	
	7.20.17	12:30	G	MW.5						Method 8260 (see back of COC) - SL	
										Metals - (see back of CQC) SL	
										Ine <del>rganic Analysis (see back of</del> COC) - SL	
						1	とと		25	Sulfide	
								,		Cn	
Compliance sample	e may require	you to report th	e tempera	ture of camples as they a	rive in the labor	ratory W	ould you l	ike the ten	perature	of samples recorded upon receipt by the laboratory? Please	
checkYes,	record and rep	ort temperature	e1	No, temperature not reque		iatory. vv	oulu you i	ike the ten	iperature	or samples recorded upon receipt by the laboratory? Please	
	0 /			rature is not requested.		1-5-2-00-5-					
RELINQUISHED-BY	2	DATE / TIME 7.19.17	Received	0511	Date / Time	REQUES	TED CON	MPLETION	IDATE	PHONE:  FAX:	
Relinquished by		19:00	Paraivad	hu HIE	11:30 Date / Time		MATRI	X TYPE		CLIENT:	
Silliquiaried by		Date / Time Received by					WW = wa	ste water		ADDRESS:	
Relinquished by		Date / Time	S=	L = Liquid soil	SL = s	sludae	CITY, STATE ZIP:				
				A = Air SD = Solid CDPHE REPORT REQUIRED				INVOICE TO:			
Database Entry By			Date	7/21/17		PWSID	#			ADDRESS:	
		<b>)</b>		(/41/1/		Sam	ple Kit Se	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Batch 24*5664*2

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs			Name: VIM CS SAMP	LER ten Xirt
Simple No. S1 A - 19 3	SAMPLE (	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES R	EQUESTED
	7.10.17	13:15	G	MW-6			WW	1	5	Method 8260 (see back	of COC) - SL
			,							Metals - (see back of Co	OC) SL
										Inorganic Analysis (see	back of COC) - SL
checkYes,	record and rep	ort temperature	<b>).</b>	ture of samples as they an No, temperature not reque rature is not requested.	sted.	ratory. V		like the ten	nperature	of samples recorded upon recei	ot by the laboratory? Please
RELINQUISHED BY	1	DATE/TIME 7.017	Received	by / /	Date / Time	REQUE	STED CO	MPLETION	DATE	REPORT TO:	PHONE:
AC.	3	19:00	lpto	hold	10:00					CLIENT:	FAX:
Relinquished by		Date / Time Received by			Date / Time	e oue e gr		IX TYPE		ADDRESS:	
					Date / Time		DW = dri	nking wate		CITY, STATE ZIP:	
Relinquished by		Date / Time Received by				Α	= soil = Air	SD =		INVOICE TO:	
omeneselengyby			150000000000000000000000000000000000000			PWSI		ORT REQUI		ADDRESS:	And the second of the second o
Paduase Entry Dy	ſ	N4Q(	Date	7/12/17		Sa	-)	ent? Yes		CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

	THE RESERVE TO A PERSON NAMED IN	-	-
Batch:			
Datell.			

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY											SAMPLER A
Client No.	CLIENT:		St	ratus Compar	nies - Ste	wart	Labs			Name: CAC	SHURT
Sample No.	SAMPLE	COLLECTION	INFO					QC	Total	Signature:	
S10-	Date	Time	Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	Report Needed	No. of Cont.		LYSES REQUESTED
	7-10-17	13:15	GI	M W-(	,	,	とと	1	8	Method 8260 (se	ee back of COC) - SL
										Metals - (see ba	ck of COC) SI_
										inorganic Analy	sis (see back of COC) - SL
	· ·										
									Mark 20. Walliam Surve		
check. Yes,	es may require record and rep	you to report the ort temperature	ie tempera ∋. ' <u>~</u> l	No, temperature not requ	rrive in the labor ested.	atory: W	ould you l	lkethetem	perature i	offsamples recordediu	pon receipt by the laboratory? Please
the second of th	the state of the s	the second section is the second section of		rature is not requested.	with the comment of the state of the						
RELINQUISHED BY	$\prec$	PATE TIME	Received	/ )	Date / Time	i e	al Pieol	VIPLETION	IDATE	REPORT TO:	PHONE:
		16.30	CZ	F7/19/17	16:30					CLIENT:	FAX:
Relinquished by		Date / Time	Received	ру	Date / Time		WW = wa	IX TYPE iste water nking water		ADDRESS:	
Relinquished by		Date / Time	Received	by	Date / Time	S:=	L = Liquid	Siz=	sludde	CITY, STATE ZIP:	4
				•	22.07 1.110	A I	Air Frierer	SD = ORTREQUI	Solid RED	INVOICE TO:	
Database Entry By			Date	The many Valley All Marks	V - 4N	PWSID	*			ADDRESS:	
					the street of	Sat	ni d KitiS	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

BACHELSHER

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compan	ies - Ste	wart	Labs			Name: Jayes	Stewart
Sample No. <b>S10-</b> 202	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES F	REQUESTED
NZB	7.19.17	12:40	GI	MW-6			<b>ww</b>			Method 8260 (see back	of COC) - SL
										Metals - (see back of Co	OC) SL
									2	Inorganic Analysis (see	back of COC) - SL
								1	爱	Sulfide	
									1	Cn	
				ture of samples as they ar No, temperature not reque		ratory. W	ould you	like the ten	nperature (	of samples recorded upon recei	pt by the laboratory? Please
Leaving this field I	olank implies t	hat the incomi	ng tempe	rature is not requested.							
RELINQUISHED BY		7.20.17	Received	by	7/2///7	REQUE	TED CO	MPLETION	DATE	REPORT TO:	PHONE:
	, 7	19:00	bt	Nullie	11:30					CLIENT:	FAX:
Relinquished by		Date / Time	Received	by	Date / Time			IX TYPE		<u> </u>	
						DW = drir	aste water nking wate	r	ADDRESS:		
Relinquished by		Date / Time	Received	Бу	Date / Time		L = Liquic = soil	SL =	sludge	CITY, STATE ZIP:	
						A = Air SD = Solid  CDPHE REPORT REQUIRED			INVOICE TO:		
Database Entry By			Date			PWSID#				ADDRESS:	
JDW 7/21/17						Sample Kit Sent? Yes / No. CITY, STATE ZIP:					



Baleir

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: ( PAGE \_\_\_\_ OF \_\_\_\_

			-						
EC USE ONL Client No	CLIENT:			Stratus Comp	anies -	ACZ			Name: JR SAMPLER SELECTION
FOR THE STATE OF T	CAMBLE	COLLECTIO	N. IV.E0						+
Sample No.	SAMPLE	COLLECTIO	ON INFO			Matrix	QC Report	Total No.	Signature:
	Date	Time	Grab / Comp	CLIENT SAMPLE IDEN	TIFICATION	Туре	Needed	Cont.	ANALYSES REQUESTED
0.2171V	7/19/17	12:40		14VW-6		N	Y		Phenois
									(Total Organic Carbon) \ (7 C Oul)
									Method 8279 (all normal compounds, including those below)
									Benzyl Butyl Phthalate
									Bis(2-ethylhexyl) phthalate
									Di-n-butyl Phthalate
									Diethyl Phthalate
									Dimethyl Phthalate
									Di-n-octyl Phthalate
									1,4-Dioxane
									Benzoic Acid
									Bencyl alcohol
	6.								2-Methylphenol
Compliance	samples may	require you t	o report the te	mperature of samples as th	ey arrive in th	e laborator	y. Would yo	ou like the te	mperature of samples recorded upon receipt by the
Leaving thi	s field blank i	mplies that t	he incoming t	emperature is not reques					
RELINQUISI	HED BY		Received by	Date / Time	MEQUESINE	J (c.0).7ii ldi.	TION DATE		PHONE: 970 224 6600
An C		7.4.17	CTF 7	19/17					
		14:30	7	1430					FAX:
Relinquished	by	Date / Time	Received by	Date / Time	14 44 500 × 1640	MATR	IX TYPE	o verdele	Steernt Lukes
:						WW = wa	ste water iking water	Was S	ADDRESS:
									CITY, STATE ZIP:
Relinquished	l by	Date / Time	Received by	Date / Time	S = S	SOIL Air	SL =	sludge = Solid	INVOICE TO:
					C	DPHE REP	ORT REQUIR	ED.	
Database En	thy By		Date		PWSID#				ADDRESS:
					Sa Sa			No	CITY, STATE ZIP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

ENGINEE PARA

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:	SAMPLE COLLECTION INFO												
Sample No.	SAMPLE	COLLECTION	Grab / Comp	CLIENT SAMPLE	DENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES RE	EQUESTED			
	7-11-17	13:60	G	MW-11			WW	1/	5	Method 8260 (see back o	of COC) - SL			
										Metals - (see back of CO	C) SL			
										Inorganic Analysis (see	back of COC) - SL			
Compliance sample check. Yes,	es may require record and rep	you to report the	e tempera	ture of samples as they ar	rive in the labo	ratory. W	ould you	like the ten		of samples recorded upon receip	t by the laboratory? Please			
The service of the se		The second second		rature is not requested.										
RELINQUISHED BY		DATE/TIME	Received	by	Date / Time 7/12/17	REQUES	STED CO	MPLETION	DATE	REPORT TO:	PHONE:			
7	0 /	20.20	Unto	Dallie	10100					CLIENT:	FAX:			
Relinquished by			Received	by	Date / Time			X TYPE						
						WW = waste DW = drinkir		nking wate	rii 1833	ADDRESS: CITY, STATE ZIP:				
Relinquished by		Date / Time	Received	by	Date / Time	S=	L = Liquid = soil = Air	SL = SD =	sludge	INVOICE TO:	7			
						CI	OPHE REP	ORT REQUI	RED	ADDRESS:				
			Date			PWSID	W. William		No. of the second					
	Ų.			7/13/17		Sar	mple Kit S	ent? Yes	/ No ***	CITY, STATE ZIP:				



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

В					
ы	а	Đ		8	
· ·	77.		-	77.5	 ٠:

Telephone: (970) 226-5500

-				
in the	201	oin	nile	× 1
- 1 4	au:	11C	1111	7. I

	CLIENT:		S	tratus (		Name: Ja	SAMPLER MES STOWERT				
Sample No	SAMPLE	COLLECTIO	ON INFO					QC.	Total No.	Signature:	4-1
	Date	Time	Grab / Comp	CLIENT SA	AMPLE IDENT	TIFICATION .	Matrix Type	Report Neede	Total No. of Cont.		ANALYSES REQUESTED
	7-11-17	13:50	G	MW	- 11		ww	4	7		270 (see back of COC) - ACZ
											015 (see back of COC) - ACZ
										Total Orga	anic Carbon - ACZ
								1			
						= = ·	-				
	H						-		-		
	Ř						-		-		
	B										
										-	
	B										
Compliance	e <b>samples</b> ma	require you.	o report the te	moerature of	samples as the	ev arrive in th	e labora	ione We	l uldevousliké	the temperati	ire of samples recorded upon receipt by the
A CONTRACTOR OF THE PARTY OF TH	is field blank i						200 1 1000	0.45			
RELINQUIS		7-11-17	Received by		Date / Time	ೣೣಽಀಽಽ	Б (СОМ) <del>г</del>	didniGN	ĐATĒ	REPORT TO:	PHONE:
	11	17:00	1 -67	Willia	1700						FAX:
				, ,						CLIENT:	
Relinquishe	d by	Date / Time	Received by		Date / Time		MATRIX				
							DW = 0	vaste wa Irinking v	vater	ADDRESS:	
						"Apple	L = Liqu	ıld ,	and the	CITY, STATE ZI	P:
Relinquishe	d by	Date / Time	Received by		Date / Time	S=8	oil	SL	= sludge  = Solid	2	and the second
Database E			DEG			PWSID#	VII.	SD	= Solid	INVOICE TO: ADDRESS:	
						Sampl	le Kit Ser	nt? Yes	/ No	CITY, STATE ZI	P:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch: 24 67.7777

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compar	ies - Ste	wart	Labs			Name: Janes SAMP	Jen X 1
Sample No. S10- 202	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES R	REQUESTED
	7.19.17	13:20	G	MW-11			WW W			Method 8260 (see back	of COC) - SL
										Metals - (see back of Co	OC) SL
					·				. 4	Inorganic Analysis (see	back of COC) - SL
								1	授	Sulfide	
									1	Cn	
				ture of samples as they a <b>No, temperature not requ</b> e		ratory. W	ould you l	ike the ten	nperature (	of samples recorded upon receip	ot by the laboratory? Please
Leaving this field b	lank implies	hat the incomi	ng tempe	rature is not requested.							
RELINQUISHED BY	*<1	1.20.17	Received	by	Date / Time 7/21/17	REQUES	TED COM	VPLETION	DATE	REPORT TO:	PHONE:
Jun 3	, 1	19:00	( bto	in till	11:30					CLIENT:	FAX:
Relinquished by		Date / Time	Received	by	Date / Time			X TYPE			
							DW = drir	ste water king water	,	ADDRESS:	
Relinquished by		Date / Time	Received	by	Date / Time	S=	L = Liquid soil : Air	SL =	sludge Solid	CITY, STATE ZIP:	-
								ORT REQUI		INVOICE TO:	
Database Entry By			Date			PWSID	#			ADDRESS:	
	Ų	MK		7/21/)	7	Sam	ple Kit Se	ent? Yes	/ No	CITY, STATE ZIP:	



Enerb

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: ( PAGE \_\_\_\_ OF \_\_\_

Cient No.	CLIENT:			Stratus	Comp	anies -	ACZ		:	Name: 1	2 SAMPLER Sterrent
Sample No.	SAMPLE	COLLECTIO	ON INFO							Signature:	du (
	Date	Time	Grab / Comp	CLIENT SAM	MPLE IDEN	TIFICATION	Matrix Type	QC Report Needed	Total No. of Cont.	C	ANALYSES REQUESTED
PEANAN	7/9/17	13:20	6	MAN -	11		W	Y		Phenols	
										Total Orga	anic Carbon
										Method 8270	ঝা normal compounds, including those below)
											utyl Phthalate
										Bis(2-eth	ylhexyl) phthalate
					100 TO 10					Di-n-buty	l Phthalate
										Diethyl P	hthalate
										Dimethyl	Phthalate
										Di-n-octy	l Phthalate
										1,4-Dioxa	ine
										Benzoic A	Acid
										Bencyl al	cohol
										2-Methyl	ohenol
Leaving thi	s field blank i	mplies that t	he incoming t	temperature is	not reques	ted.			The second secon		amples recorded upon receipt by the
RELINQUIS	HEDEY	7.19.17	Received by	7/ / <sup> </sup>	Date / Time	REQUESTE	J GOMILL	ETION DATE		REPORT TO:	PHONE:
eft.	OV	14:27	CTF	119/17	1430						FAX:
Relinguished	lbv	Date / Time	Received by		Date / Time	in the trade of the	MATE	IX TYPE	deport of the law of	CLIENT:	
	,		,		Date, Time		WW = wa	ste water king water	<b>*</b>	ADDRESS:	-
Relinguished	l by	Date / Time	Received by		Date / Time	S = 9	L = Liquid	SL=	sludge	CITY, STATE Z	IP:
		_3.07 1.1110	,			A = /	Air	SD =	= Solid	INVOICE TO:	Silternamentance expedit a renegli (*)
Database Er	itry By		Date			PWSID#				ADDRESS:	
						Sa	mple Kit S	ent? Yes /	No	CITY, STATE Z	IIP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

ener.		
-------	--	--

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:			ratus Compan			Name: SAMP	Stewart			
Sample No. S. G. 21	SAMPLE Date	COLLECTION Time	Grab / Comp	CLIENT SAMPLE	DENTIFICATION	ON .	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES R	EQUESTED
135 A	7-11.17	15:20	GI	MW- 17	~		NN	4	5	Method 8260 (see back	of COC) - SL
										Metals - (see back of CO	OC) SL
										Inorganic Analysis (see	back of COC) - SL
								711			
checkYes,	record and rep	you to report the	e tempera e.	iture of samples as they ar <b>No</b> , temperature not reque	rive in the labor sted.	ratory. W	ould you	like the ten	nperature	of samples recorded upon receip	t by the laboratory? Please
	1			rature is not requested.							
RELINQUISHED BY		Z-[1-]	Received	by	Date / Time 7/12/17	REQUES	STED CO	MPLETION	DATE	REPORT TO:	PHONE:
- June	0 1	20:20	Vot	in off	10:00					CLIENT:	FAX:
Relinquished by		Date / Time		by	Date / Time		MATRIX TYPE  WW = waste water			ADDRESS:	
						ž.,	DW = dri	nking wate		CITY, STATE ZIP:	
Relinquished by		Date / Time	Received	by	Date / Time	S = soil SL = sludge A = Air SD = Solid			Solid	INVOICE TO:	
Database Entry sys			Cachemen			PWSID		ORT REQU	RED TO	ADDRESS:	
ORIGINAS CIRTY DY	767		Date	7/)3/17		San	nple Kit S	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

		鸭	Ħ		П
В	a	U.		1	

Telephone: (970) 226-5500

	Facsimile: (	PAGE	OF	
--	--------------	------	----	--

EG USE ONL Client No. (	CLIENT:		S		Name:	lame:								
Sample No.	SAMPLE	COLLECTIO	N INFO					QC	Taran Na	Signature	1	form >	1	
51/2	Date	Time	Grab / Comp	CLIENT SA	AMPLE IDEN	TIFICATION	Matrix Type	Report Neede	Total No. of Cont.		1	ANALYSES RE	QUESTED	1
	7.11.7	15:20	<b>G</b> 7	MJ	.17		ろろ	7	X	Method	827	0 (see back	of COC) - A	CZ
			,									5 (see back		ACZ
										Total O	rgar	nic Carbon -	ACZ	
							1							
	-						1			De .				
							-	-						
							-			-				
						·	-		-				<del></del>	
							<del>                                     </del>							
Compliance	samples may	require you t	o report the te	mperature of	samples as th	ey arrive in th	ieilabora					of samples rec	arded upon rec	ceipt by the
the second secon	and the same of th	mplies that t	he incoming	temperature	is not reques	ted.				1.54.80				Friedly.
RELINQUISH	50/	PATE/TIME	Received by	-11	Date / Time	(- 0 = 5  =	D COMP	LETION	DATE	REPORT TO		HONE:	y i y	
1	- (1) A		Cel	1/19/17	1700						F	AX:		
	~	17:00	1	/ ('	1200					CLIENT:				
Relinquished	by	Date / Time	Received by		Date / Time		MATRIX	TYPE						
					y -		DW = 0	As all the second	A STATE OF THE PARTY OF	ADDRESS:				
						DW = drinking water  L = Liquid				CITY, STATE	E ZIP:	4		
Relinquished	by	Date / Time	Received by		Date / Time					Y .				
	•					A = A	Air	SD	) = Solld	INVOICE TO	);			DAGE TO SERVICE TO SER
Dalabase Ent	ity By		Date			PWSID#				ADDRESS.				
						Samp	le Kit Ser	nt? Yes	/ No	CITY, STATE	E ZIP:			



# Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Clier	nt: Stratus Initials: JDW Date: 7/12/17			MST/MDT
	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?			
2	Were samples on ice or in a refrigerated state upon retrieval?			
	Courier Initials: 1 Date: 7/1/17 Time: 20, 20			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?			
4	Chain of Custody (COC) present?	/		
5	Sample bottles intact? *	/		
6	Samples on blue-ice?			
7	Samples on wet ice?			
8	Samples received within 4 hours of sampling?		/	
9	Record temperature of sample bottles within cooler with infra-red	thermomete	r.	
	Temp °C   7.8 °	Yes	No	NA
10	Sample thawed and free of any ice? *			
11	COC complete, legible, signed and dated?			
12	Labels on bottles complete and legible? *			
13	COC in agreement with sample bottle labels? *			
14	Proper container used for analyses requested? *			
15	Samples requiring preservation preserved correctly? *			
16	Sufficient sample volume for analyses requested? *			
17	Samples within holding times for analyses requested? *			
18	Samples requiring no headspace are free of headspace? *			/
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	<pre> &lt; green pe</pre>	ea,	> green pea
	* If no, document on Chain of Custody.			
Notes	o.			



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Bacheles

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

	PAGE	OF
--	------	----

SEC USE ONLY Client No.	CLIENT:			ratus Compan	ies - Ste	wart	Labs			Name: Janes SAMP	Stevert	
Sample No. S10-202	SAMPLE Date	COLLECTION Time	Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES R	EQUESTED	
1910	7.19.17	13:00	61	MW.12			ww	4		Method 8260 (see back	of COC) - SL	
				•					Metals - (see back of COC) SL			
										Inorganic Analysis (see	back of COC) - SL	
								1	X	Sulfide		
									1	Cn		
				ture of samples as they ar		ratory. W	ould you	like the ten	perature	of samples recorded upon receip	t by the laboratory? Please	
			The same of	rature is not requested.								
RELINQUISHED BY	51	7.20.17	Received	by	Date / Time 7/21/17	REQUES	STED CO	MPLETION	DATE	REPORT TO:	PHONE:	
7	2. 1	19:00	1 Let	mille	11:30					CLIENT:	FAX:	
Relinquished by		Date / Time	Received	by	Date / Time	MATRIX TYPE				ADDRESS:		
						WW = waste water DW = drinking water						
Relinquished by		Date / Time	Received	by	Date / Time	L = Liquid S = soil SL = sludge			sludge	CITY, STATE ZIP:		
						A = Air SD = Solid CDPHE REPORT REQUIRED				INVOICE TO:		
Database Entry By			Date			PWSID	#			ADDRESS:		
		JYV.		7/21	/17	Sar	nple Kit S	ent? Yes	/ No	CITY, STATE ZIP:		



Baleit

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: ( PAGE \_\_\_\_ OF \_\_\_

EC USE ONL Client No	CLIENT:	,		Stratus	s Comp	anies -	ACZ		Name: 🜙	R SAMPLER SAMPLER			
Sample No.	SAMPLE	COLLECTIO	ON INFO							Signature:	1		
	Date	Time	Grab / Comp	CLIENT SA	MPLE IDEN	TIFICATION	Matrix Type	QC Report Needed	Total No. of Cont.	C	ANALYSES REQUESTED		
WW TAR	7/19/17	13:00	6	Ma	-14		16	Y		Phenois			
							'			Total Org	anic Carbon		
											(all nermal compounds, including those below)		
										The second secon	utyl Phthalate		
										Bis(2-eth	ylhexyl) phthalate		
										Di-n-buty	/I Phthalate		
										Diethyl P	hthalate		
										Dimethyl Phthalate			
										Di-n-octyl Phthalate			
										1,4-Dioxane			
										Benzoic	Acid		
										Bencyl a	Icohol		
										2-Methyl			
Leaving this	s field blank i	mplies that t	he incoming t	temperature i	s not reques	ted.					samples recorded upon receipt by the		
RELINQUISI	HED BY	DATE/TIME	Received by	_ / 1	Date / Time	REQUESTE	) GOMPLI	HON DATE		REPORT TO:	PHONE:		
1		14:20	ac	1(9/17	1430						FAX:		
Relinquished	by	Date / Time	Received by		Date / Time		* MATR	IX TYPE CAS	9-1-3690-14	CLIENT:			
						WW = waste water DW = drinking water L = Liquid				ADDRESS:			
Relinguished	l bv	Date / Time	Received by		Date / Time	L = Liquid S = soil SL = sludge				CITY, STATE 2	ZIP:		
•	,					S = soil SL = sludge A = Air SD = Solid CDPHE REPORT REQUIRED				INVOICE TO:			
Database En	try By		)  2:36			PWSID #				ADDRESS:			
						- and ⊶ Sa	mple Kit S	ent? Yes /	No	CITY, STATE 2	ZIP:		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Englisher englisher

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY	CLIENT:			ratus Compan	ies - Ste	wart	Labs		Name: James Stampler	wift		
Sample No S1 ()-1 /2/-	SAMPLE Date	Time	Grab / Comp	CLIENT SAMPLE I	DENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES REQU	ESTED	
	7.12.17	10:00	G	MW-13			NW		(0	Method 8260 (see back of C	COC) - SL	
			1							Metals - (see back of COC)	SL	
										Inorganic Analysis (see bad	ck of COC) - SL	
										COD		
check. Yes.	record and rep	ort temperature	).	No, temperature not reque	sted.		ould you	like the ten		of samples recorded upon receipt by	the laboratory? Please	
Leaving this field I	olank implies t	hat the incom	ing tempe	rature is not requested.								
RELINQUISHED B		7.12.17	Received		Date / Time 7/13/17	REQUES	TED CO	MPLETION	DATE	REPORT TO:		
4	B. 1	19:00	-par	whe	10:00					CLIENT:		
Relinquished by		Date / Time	Received	by	Date / Time	WW = waste water DW = drinking water L = Liquid				ADDRESS:		
Relinquished by		Date / Time	Received	by	Date / Time				The state of	CITY, STATE ZIP:		
Talliquiaried by		Date / Time	, COGIVED	~,	Date / Time				Solid	INVOICE TO:		
Database Entry By			Date			-	# 35	The second second		ADDRESS:		
		DV		7/3/6		Sample Kit Sent? Yes / No				CITY, STATE ZIP:		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

COL			
	arin i	A STATE OF	inde in:
t Iro	241		
S. Stephen	dia.		i, jii, jii,

Telephone: (970) 226-5500

Facsimile: (

EC USE ONL Client No	CLIENT:		S	tratus C	ompan		Name:	Mes Steelast			
Sample No.	SAMPLE	COLLECTIO	N INFO				Matrix	QC	Total No.	Signature:	
	Date	Time	Grab / Comp	CLIENT SAMPLE IDENTI		TFICATION	Matrix Type	Report Neede	of Cont.		ANALYSES REQUESTED
Maria	7-12-17	0:00	G	MW	-13		とと	E	400	Method 82	270 (see back of COC) - ACZ
									die :	Medignia	The COCY TO
									3	Total Orga	anic Carbon - ACZ
									<b>P</b>		
						the second secon					
				V		The Table of					
			to the same of the			124	e labora	tory. Wo	uld you like	the temperati	ure of samples recorded upon receipt by the
	s field blank i				Date / Time		DOME	ETION	DATE	REPORT TO:	
RELINQUIS		DATE TIME	Received by		Date / Time	REGUESTE	D COIVIE	LETION	DATE		PHONE:
	0 1	7-13-17			1-						FAX:
		15:50	CFF	7/13/17	1550					CLIENT:	
Relinquished	d by	Date / Time	Received by	( . // /	Date / Time	10 (N)	MATRIX	( TYPE			
					. *	WW = waste water  DW = drinking water				ADDRESS:	
						L ⇒ Liquid				CITY, STATE ZI	P:
Relinquished	d by	Date / Time	Received by		Date / Time					INVOICE TO:	
73999889999973	91204503030303		DEG			PWSID#				ADDRESS:	
Database Er	шу Бу									CITY, STATE Z	P:
						Sample Kit Sent? Yes / No					



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch-21/5 67/97

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SECLISION NO.	CLIENT:		St	ratus Compani	ies - Ste	wart	Labs			Name: James Stewart	
Sample No. S10-202	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE I	DENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES REQUESTED	
123	7.20-17	00:01	Con	MW-13			らと	4	3	Method 8260 (see back of COC) - SL	
			,							Metals - (see back of COC) SL	
										Inorganic Analysis (see back of COC) - SL	
										<del>Sulfid</del> é	
									1	solfide	
Compliance sample check. Yes Leaving this field	es may require , record and rep blank implies	oort temperatur	e Ing tempe	No, temperature not reque trature is not requested.	rive in the labo sted.	ratory. V	Vould you	like the ter	nperature	of samples recorded upon receipt by the laboratory? Please	
RELINQUISHED BY	<u>'</u>	PATE / TIME	Received	by	Date / Time 7/21/17	REQUE	TED CO	MPLETION	DATE	REPORT TO: PHONE:	
	12 1	19:00	Vat	Twile	11:30	MATRIX TYPE  WW = waste water  DW = drinking water  L = Liquid				FAX:	
Relinquished by		Date / Time	Releived	Dy	Date / Time					ADDRESS:	
Relinquished by		Date / Time	Received	by	Date / Time				sludge	CITY, STATE ZIP:	
				-					Solid RED	INVOICE TO:	
Dalabase andy by			Date			PWSID#				RECORD	
		DM		7/2//17		Sample Kit Sent? Yes / No				CITY, STATE ZIP:	



# Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?	/		
2	Were samples on ice or in a refrigerated state upon retrieval?			
	Courier Initials: Date: 7-2019 Time: 19:68			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?		<u> </u>	
4	Chain of Custody (COC) present?			
5	Sample bottles intact? *			1
6	Samples on blue-ice?		/	1
7	Samples on wet ice?	/		1
8	Samples received within 4 hours of sampling?		/	1
0	Depart townsorture of comple hettles within accles with infer and	Ala a una a una un a 4-	_	
9	Record temperature of sample bottles within cooler with infra-red	tnermomete	г.	
	Container #			
	Temp °C 4.30	Yes	No	T NA
10	Sample thawed and free of any ice? *	165	NO	IVA
11	COC complete, legible, signed and dated?			1
12	Labels on bottles complete and legible? *			1
13	COC in agreement with sample bottle labels? *	N		-
14	Proper container used for analyses requested? *	V		
15	Samples requiring preservation preserved correctly? *	V		]
16	Sufficient sample volume for analyses requested? *			
17	Samples within holding times for analyses requested? *	V		
18	Samples requiring no headspace are free of headspace? *	<b>V</b>		
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	_ < green pe	ea,	> green p
	* If no, document on Chain of Custody.			
Nota-	D.L. La Cidio inchi			
Notes	: Put into Pride upon ario	4		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

BAIGH ZUG WE

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs		×	Name: James Standart
Sample No. S1 9- 208	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED
	7.2517	17:00	GI	MW-13		1	WW	4	•	Method 8260 (see back of GQC). SL
										Metals (see back of CQC) SL
										In <del>organic Analysis (see back of COC)</del> -SL
										Sulfide
									)	Cn
			* 1	-						
			:							
					<del></del>					
Compliance sample	es may require	you to report the	ne tempera	ture of samples as they ar	rive in the labor	ratory. W	ould you	like the ten	nperature	of samples recorded upon receipt by the laboratory? Please
Leaving this field	blank implies	that the incom	ing tempe	No, temperature not reque prature is not requested.	sted.					
RELINQUISHED B	Name and Address of the Owner, where the Person of the Owner, where the Person of the Owner, where the Owner, which is the Owner, which	DATE / TIME			Date / Time	[[[] [] [] [] [] [] [] [] [] [] [] [] []	्रातका स्ट्रा इ.स.च्या		6 e7 e 6	REPORT TO: PHONE:
17-0	5	7.25.17	11/2	hadle	/8:30 Date / Time			14. ×		FAX:
Relinquished by		Date / Time	Received	by	Date / Time		MATH	IX TYPE		ADDRESS:
						1	DW = dri	nking wate		CITY, STATE ZIP:
Relinquished by		Date / Time	Received	by	Date / Time	S =	soil Air	d SL = SD =	sludge Solid	INVOICE TO:
**************************************						COPHE REPORT REQUIRED PWSID #			The second second second	ADDRESS:
Database Entry By		0 DW	Date	7/27/	//7			ent? Yes		CITY, STATE ZIP:



# Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

	To be filled and by lebourtery couries if anythering	Vac	No.	I NIA
	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?			
2	Were samples on ice or in a refrigerated state upon retrieval?			
	Courier Initials: 1 Date: 7.25.17 Time: 18:30			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?			
4	Chain of Custody (COC) present?	✓		
5	Sample bottles intact? *	V		
6	Samples on blue-ice?			
7	Samples on wet ice?			
8	Samples received within 4 hours of sampling?	/		
	Container # Temp °C 4.80	Yes	No	NA
	Temp C 19.80	Yes	No	NA
10	Sample thawed and free of any ice? *			
11	COC complete, legible, signed and dated?	<b>V</b>		
12	Labels on bottles complete and legible? *	V		.,
13	COC in agreement with sample bottle labels? *			
14	Proper container used for analyses requested? *			
15	Samples requiring preservation preserved correctly? *	V		
16	Sufficient sample volume for analyses requested? *	V		
17	Samples within holding times for analyses requested? *	V		
18	Samples requiring no headspace are free of headspace? *			V.
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	_ < green pe	a,	> green pea
	* If no, document on Chain of Custody.			
Notes	: put into fridge ucon arive	2		•4
	The state of the s			



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Telephone: (970) 226-5500

Facsimile: (970) 226-4946 PAGE \_\_\_\_ OF \_\_\_

	CLIENT:			ratus Compan	ies - Ste	wart L	.abs			Names SAMPLER STELL		
Sample No	SAMPLE (	COLLECTION Time	Grab / Comp	CLIENT SAMPLE	DENTIFICATIO	N/I	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES REQUESTED		
150 7	7-10-17	14:30	GI	M W-15	>	1	7 N	4	5	Method 8260 (see back of COC) - SL		
										Metals - (see back of COC) SL		
										Inorganic Analysis (see back of COC)	- SL	
Compliance samples check. Yes, re	may require ecord and rep	you to report the	e tempera	ture of samples as they ar No, temperature not reque	rive in the labor sted.	ratory. Wo	uld you	like the ten	nperature	of samples recorded upon receipt by the laboratory?	Please	
	election of the real	hat the Incomi	ing tempe	rature is not requested.								
RELINQUISHED BY	$\times$	DATE/TIME 7-10-17	Received	Py 11	Date / Time 7/11/17	REQUEST	ED CO	MPLETION	DATE	REPORT TO: PHONE:		
0 - 0	1	19:00	Ste	rolle	10:00					CLIENT:		
Relinquished by		Date / Time	Received	by	Date / Time		/W = wa	IX TYPE		ADDRESS:		
Relinquished by		Date / Time	Pacaivad	by	Data / Time	L	= Liquid	nking wate	7.	CITY, STATE ZIP:		
Reiniquistied by		Date / Time	Neceived	Бу	A		S = soil SL = sludge A = Air SD = Solid  COPHE REPORT REQUIRED			INVOICE TO:		
Database Entry By			Date			PWSID #			for the second section of the second	ADDRESS:		
			70	7/12/	/Z	2	-	ent? Yes	Accessed to the second	CITY, STATE ZIP:		



## Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

C	lient: Stratus Initials: DM Date: 7/11/17	/Time:/	0:00	MST/MDT
	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?			
2	Were samples on ice or in a refrigerated state upon retrieval?	/		
	Courier Initials: 1 Date: 7:01 Time: 19:00			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?			
4	Chain of Custody (COC) present?	/		
5	Sample bottles intact? *	/		1
6	Samples on blue-ice?		/	
7	Samples on wet ice?	/		
8	Samples received within 4 hours of sampling?			
9	Record temperature of sample bottles within cooler with infra-red	thermomete	er.	
	Container #			
	Temp °C 12 20			
		Yes	No	NA
10	Sample thawed and free of any ice? *			-
11	COC complete, legible, signed and dated?			
12	Labels on bottles complete and legible? *			
13	COC in agreement with sample bottle labels? *			
14	Proper container used for analyses requested? *			
15	Samples requiring preservation preserved correctly? *			
16	Sufficient sample volume for analyses requested? *			
17	Samples within holding times for analyses requested? *		1	
18	Samples requiring no headspace are free of headspace? *			1
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	_ < green pe	ea,	> green pea
	* If no, document on Chain of Custody.			
No	tes: MW 15 needs to be resamp	led - +	TOO MI	scle
	headspace.			



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

╗			-	_		•	-	_
23						а		
4		-	and the					٠:
я	-6	43	137			и.	м	٠,
а	-	a	ж.		8:1	ь.		. :
67	·			100	ŀ	24		٠.

Telephone: (970) 226-5500

gates y 5		
Facsimi	0.	
acomin	10.	l

EGUSEOT FRANCE	CLIENT:		S	tratus	Compan	ies - A0	CZ			Name:	rives Stewart
Sample No.	SAMPLE	COLLECTIO	N INFO			Art Lean in		QC		Signature:	4-05
	Date	Time	Grab / Comp	CLIENT S	SAMPLE IDENT	TIFICATION	Matrix Type	Report Neede	Total No. of Cont.		ANALYSES REQUESTED
LULUE.	7.12.17	12:40	G1	MU	J- 15		WN	-	4	Method 8	3270 (see back of COC) - ACZ
											MUST she track of COCY MOZ
									3	Total Org	ganic Carbon - ACZ
						- 10 W - 10 to see 7					
					<del></del>						
							70				
						<del></del>					
							o laboro	Sev. MA	Wile meanwhile	71.74.74.44	ture of samples recorded upon receipt by the
					i samples as m						take of salarples lecorated upon heceipt by the
RELINQUIS			Received by		Date / Time					REPORT TO:	PHONE:
1mg	MX	7.12-17	1 8 /	On.	7-12-17						PHONE:
	. X . 1		1 fee	the							FAX:
		C:30	4	10	16:30					CLIENT:	
Relinquishe	d by	Date / Time	Received by		Date / Time	With the second	MATRIX	1			
										ADDRESS:	
										CITY, STATE 2	710-
Relinquishe	d by	Date / Time	Received by		Date / Time	S = s	oil 7	SL	= sludge	J. I., JIAIL	
	•					A = A	Vir	SD	= sludge ) = Solid	INVOICE TO:	
Database E	ntry By		Date			PWSID#				ADDRESS:	- 17
						Samp	le Kit Sei	nt? Yes	/ No	CITY, STATE 2	ZIP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

BACH 245/ASE

Telephone: (970) 226-5500

Facsimile: (970) 226-4946 PAGE \_\_

SEC USE ONLY Client No.	CLIENT:			ratus Compan	ies - Ste	wart Labs	3		Name: Janes Stewart
	SAMPLE (	COLLECTION Time	Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED
787	7-17-17	13:00		MW-15		WW		3	Method-8260 (see back of COG) - SL
								2	Metals - (see back of COC) SL
									In <del>organic Analysis (see back of COC) - S</del> L
									Sulfide
									Cn
									method 8260
				· ·					
							ATT COMPANY		
checkYes	es may require , record and rep	you to report treort temperature	e tempera	No, temperature not reque	rive in the labor ested.		i like the tei	nperature	of samples recorded upon receipt by the laboratory? Please
THE RESERVE TO SERVE THE PROPERTY OF THE PERSON OF THE PER	the second secon			erature is not requested.					
RELINQUISHED BY	5	7.17.17	Received	by A	Date / Time 7 / 18 / 17	REQUESTED CO	MPLETIO	N DATE	REPORT TO: PHONE:
		19:00	bot	with	11:00	NAT	DIV TVDE		FAX:
Relinquished by		Date / Time	Received	т бу	Date / Time	WW = v	RIX TYPE vaste water rinking water	ar .	ADDRESS:
Relinquished by		Date / Time	Received	Тbу	Date / Time	L = Liqu S = soil	id SL =	sludge	CITY, STATE ZIP:
				A Comment		A = Air	SD : PORT REQU	= Solid	INVOICE TO:
Database Entry By			Date			PWSID#			ADDRESS:
	0			7/18/17		Sample Kit	Sent? Yes	/ No	CITY, STATE ZIP:



SECON

STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: ( PAGE \_\_\_\_ OF \_\_\_\_

EGUSEIGN Gien No	CLIENT:			Stratu	s Comp	anies -	ACZ			Name:	LIMES Stewart
											1
Sample No.	SAMPLE	COLLECTION	ON INFO				Matrix	OC Report	Total No. of	Signature:	9-17
5 1:	Date	Time	Grab / Comp	CLIENT SA	AMPLE IDEN	TIFICATION	Туре	Needed	Cont.		ANALYSES REQUESTED
										Phenels-	
1341167	7.17.17	13:00		MW-	15		NN				anic Carbon
											(all normal compounds, including those below)
										Benzy	utyl Phthalate
										Bis(2-eth	xlhexyl) phthalate
				***						Di-n-buty	l Phthalate
										Diethyl P	hthalate
	-									Dimethyl	Phthalate
										Di-n-octy	l Phthalate
										1,4-Djóxa	ane \
										Benzoic /	Acid
										Bencyl al	cohol
										2-Methyl <sub>l</sub>	phenol
Compliance	samples may	require you t	o report the te	mperature of	samples as th	ey arrive in th	e laborator	y. Would yo	u like the tem	perature of s	amples recorded upon receipt by the
Leaving this	s field blank i	mplies that t	he incoming	emperature	is not reques	led.				Orași de la constituit	
RELINQUIS	HED BY	DATE/TIME	Received by		Date / Time	REQUESTE	COMPLE	ETION DATE		REPORT TO:	PHONE:
1		14:21	179	Thol	1000						FAX:
Relinquished	lbv	Data / Time	Received by	11717	1830 Date / Time	S. Merchanis	MATO	IV TYPE		CLIENT:	
rteiiiquisiicu	Бу	Date / Timle	Treceived by		Date / Time				Colombia Bagas	ADDRESS:	
							DW = drir	ikina water		CITY, STATE Z	ID-
Relinquished	l by	Date / Time	Received by		Date / Time	S = s	oil	SL=	sludge		
						A = /	AIF CONTRACTOR	SD =	= Solid	INVOICE TO:	a comment of the comm
Database En	nvev III		Date			PWSID#				ADDRESS:	
						Sa	mple Kit S	ent? Yes /	No	CITY, STATE Z	IP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Bach 248 6767

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compa	nies - Ste	wart Labs			Name: Jaues Stewart
Sample No S1 6- / 67	SAMPLE (	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	E IDENTIFICATIO	N Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED
	7.2017	14:31)	GI	MW-	15	WW	1		Method 8260 (see back of GOC) - SL
									Metals - (see back of COC) SL
									Inorganic Analysis (see back of COC) - SL
				1			1	X	Bulfide
								1	Ca
				ture of samples as they No, temperature not req		atory. Would you	like the ter	nperature	of samples recorded upon receipt by the laboratory? Please
Leaving this field I	olank implies t	hat the incom	ing tempe	rature is not requeste				17.4 2	
RELINQUISHED BY		DATE/TIME	Received	1 by	Date / Time   7/21/17	REQUESTED CO	MPLETION	DATE	REPORT TO: PHONE:
9	01	19:00	between	hubble	11:30				FAX:
Relinquished by		Date / Time	Received	by	Date / Time		RIX TYPE		ADDRESS:
							inking wate d		CITY, STATE ZIP:
Relinquished by		Date / Time	Received	by	Date / Time	S = soil A = Air	SL = SD =	sludge Solid	INVOICE TO:
						PWSID#	ORT REQU	RED	ADDRESS:
Database Entry By		٨٨٥ر	Date	7/21/17		Sample Kit S			CITY, STATE ZIP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch: 24,56586

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	tratus Companies - Stewart Labs  Name: SAMPLER SAMPLER SAMPLER								
Sample No.	SAMPLE Date	COLLECTION	Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES F	REQUESTED	
1038	7.617	13:30	GI	M.W.11	9		NM	4	8	Method 8260 (see back	of COC) - SL	
										Metals - (see back of C	OC) SL	
										Inorganic Analysis (see	back of COC) - SL	
						•						
								,				
							•					
checkYes,	Compliance samples may require you to report the temperature of samples as they arrive in the laboratory. Would you like the temperature of samples recorded upon receipt by the laboratory? Please checkYes, record and report temperatureNo, temperature not requested.  Leaving this field blank implies that the incoming temperature is not requested.											
RELINQUISHED BY		DATE / TIME			Date / Time	REQUES	STED CO	MPLETION	DATE	REPORT TO:	PHONE:	
ful 1	Q1	18.20	1/4	the delia	7/6/17					OLIPAT.	FAX:	
Refinquished by			Regeived	by	Date / Time			XIX TYPE		CLIENT:		
						WW = waste water DW = drinking water		nking wate	r	ADDRESS: CITY, STATE ZIP:		
Relinquished by		Date / Time	Received	by	Date / Time	L = Liquid S = soil SL = : A = Air SD =		sludge Solid	INVOICE TO:			
						CI	OPHE REP	ORT REQUI		ADDRESS:		
Database Entry By	7	DM	Date	7/7/17		PWSID # Sample Kit Sent? Yes / No. 10			/ No **			



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500

Facsimile: ( PAGE \_\_\_\_ OF \_\_\_

EGUSEION Gient No	CLIENT:		S	tratus	Compan	ies - A0	Z			Name: Y	wes Stenart
Sample No.	SAMPLE	COLLECTIO	N INFO		3 F. 1975		Matrix	QC	Total No.	Signature:	
	Date	Time	Grab / Comp	CLIENT S	AMPLE IDENT	IFICATION	Type	Report Neede			ANALYSES REQUESTED
1941072	7-12-11	13:40	S	MW	-16		WA		3	Witte	270 (see back of COC) - ACZ
							_				
					samples as the		e labora	tory Wo	uld you like	the tempera	ure of samples recorded upon receipt by the
RELINQUIS	HED BY	DATE / TIME 1-12-17	Received by	ue	Date / Time 7:12:13 16:30-	A	D COMP	LETION	DATE	REPORT TO:	PHONE: FAX:
Relinquished	d by	Date / Time	Received by		Date / Time	200 R Spage 240				CLIENT:	
							DW = 0	waste wa Irinking w ud	The state of the state of the state of	ADDRESS:	ZIP:
Relinquished	d by	Date / Time	Received by		Date / Time		oil 🦠 🗎	SL: SD	= sludge <sup>53</sup> = Solid		
Database E	aury By		ĐặC			PWSID# Sampl	2. 3.50		/ No		ZIP:



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

|--|--|

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEGUSEONIY CIIGHENO	CLIENT:		St	ratus Compan		Name: JUCS SAMPLER	\r\ \					
Sample No. S-17- /49	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES REQUEST	ED	
MAS A	7.17.17	13:30	G	MW. 16			<b>WW</b>		1	Method 8260 (see back of GOC) SL		
			-							Metals - (see back of COC) SL		
										Inorganic Analysis (see back o	(COC) SL	
										Sulfide		
										Cn		
Compliance sample	es may require	you to report th	ne tempera	ture of samples as they a No, temperature not reque	rrive in the labor	ratory. W	ould you	like the ten	nperature	of samples recorded upon receipt by the	laboratory? Please	
		the sales and the sales are		rature is not requested.								
RELINQUISHED BY	1	DATE/TIME	Received	l by	Date / Time 7/18/17	REQUE	STED CO	MPLETION	DATE	REPORT TO: PHONE:		
1	P. 1	19:00	lota	h alla.	11:06					CLIENT:		
Relinquished by			Received	by	Date / Time			IX TYPE		ADDRESS:		
						2.44	DW = dri	nking water	<b>r</b>	CITY, STATE ZIP:		
Relinquished by		Date / Time	Received	by	Date / Time	S=	soil	SL =	sludge	INVOICE TO:		
						CEPHE REPORT REQUIRED			RED			
Database Entry By	N N		Date	5/110/15		PWSID			A SA	ADDRESS:  CITY, STATE ZIP:		
	Ų			7/18/17		Sar	nple Kit S	ent? Yes	/ No	OIT TOTALE ZIF.		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

PERSONAL PROPERTY.	
	4 144
	× 1 PI
i ana babba	dddd

Telephone: (970) 226-5500

Face	imai	la.
Facs	21111	Ie:

ECUSE ONL Client No. CLIENT:			Stratus Companies - ACZ					Name: Jaw C	SAMPLER Stewart	
Sample No. SAMPLE	COLLECTIO	ON INFO							Signature:	-2/2/
St () Date	Time	Grab / Comp	CLIENT SA	MPLE IDENT	TIFICATION	Matrix Type	QC Report Needed	Total No. of Cont.	/ /	SES REQUESTED
									Phenols -	
7.17.17	13:30		·ww.	110		NN		1	Total Organic Car	
								1		compounds, including those below)
									Benzyk Butyl Pht	
									Bis(2-ethylhexy)	The state of the s
									Di-n-butyl Phtha	ate
									Diethyl Phthalate	
									Dimethyl Phthala	nte
									Di-n-octyl Phthal	ate
				5 × ½					1,4-Dioxane	
									Benzóic Acid	1
									Bericyl alcohol	\
									2-Methylphenol	
Compliance samples may	y require you t	o report the te	mperature of	samples as th	ey arrive in th	e laborator	y. Would yo	u like the tem	perature of samples re	corded upon receipt by the
Leaving this field blank	mplies that t	ne incoming	emperature i	s not request	led.	40.27		**		
RELINQUISHED B	DATE / TIME	Received by	1/ 1	Date / Time	REQUESTE	D COMPLE	TION DATE		REPORT TO: PHONE:	<u></u> }∞ <del>q</del>
1		ar	1/19/17	1430					FAX:	
Dalia-wished by	14:30	Desciused by							CLIENT:	
Relinquished by	Date / Time	Received by		Date / Time		WW = wa	ste water	STANDARD COM	ADDRESS:	
						DW = drir	ste water king water			
Relinquished by	Date / Time	Received by		Date / Time	S=s	L = Liquid soil	- SL =	sludge	CITY, STATE ZIP:	
		,			S = soil SL = sludge A = Air SD = Solid CDPHE REPORT REQUIRED				INVOICE TO:	
		P-CHARLOCH MACHINE				CHANE INCH	SIAI MEMORA		ADDRESS:	
Database Entry By		Date			PWSID#	The same of the				
					Sa	mple Kit S	ent? Yes /	No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525 BAIGH ELEGATA

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs			Name: GMCS STEW	act
Samole No. Si 9-9-92	SAMPLE Date	COLLECTION	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUEST	ED
1121	7.20.17	14:45	G	MW-16			いい	\/		Method 8260 (see back of COC	;)-SL
			7							Metals - (see back of COC) SL	
										Inorganic Analysis (see back o	rcoc) - SL
									l	Sulfide	
							,				
					¥.						
checkYes,	record and rep	ort temperature	).	No, temperature not reque		atory. W	ould you	like the ten	nperature	of samples recorded upon receipt by the	aboratory? Please
RELINQUISHED BY		DATE / TIME		rature is not requested.	Date / Time	্র ভা <b>রতা</b> গার	SED CO	MREGION	R = 7: 11 5 100	REPORT TO: PHONE:	
1-9	6	7.2017		is on	2/21/17					FAX:	
Relinquished by	7	19:00 Date / Time	Received	h while	Date / Time		MATR	IX TYPE		CLIENT:	
		Dato / Timo		-,		3	WW = wa	aste water nking wate	•	ADDRESS:	
Relinquished by		Date / Time	Received	by	Date / Time		L = Liquid soil	SL=	sludae	CITY, STATE ZIP:	
								ORT REQUI	Solid	INVOICE TO:	
Database Entry by			Date	7275		PWSID				ADDRESS:	
		DW		4/ = 1/ /		Sar	nple Kit S	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Eatch 24 (516) 20

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compar	nies - Ste	wart	Labs			Name: Lucs	Steward
Sample No.	SAMPLE	COLLECTION	INFO					QC	Total	Signature:	
S16-4-2	Date	Time	Grab / Comp	CLIENT SAMPLE	IDENTIFICATI	ON	Matrix Type	Report Needed	No. of Cont.	ANALYSES	REQUESTED
	7.2817	16:30	G	MW-19			こと	1/	3	Method 8260 (see back	of COC) - SL
	7-27-17			•					1	Metals - (see back of C	OC) SL
										Inorganic Analysis (se	e back of COC) - SL
									1	Sulfide	
									1	Cn	
									-		
				ture of samples as they a No, temperature not requ		ratory. W	ould you l	ike the ten	perature o	of samples recorded upon rece	ipt by the laboratory? Please
				rature is not requested.							
RELINQUISHED	A	PATE / TIME -	Received	by		REQUES	STED COM	<b>VPLETION</b>	DATE	REPORT TO:	PHONE:
7	2 1	18:30	17/	Ma lla	7/31/17						FAX:
Relinquished by		Date / Time	Received	by	Date / Time		MATRI	X TYPE		CLIENT:	
		72717					WW = wa DW = drir	ste water king water		ADDRESS:	
Relinquished by		18:30 Date / Time	Received	by	Date / Time	S=	L = Liquid : soil		sludge	CITY, STATE ZIP:	
						A = Air SD = Solid COPHE REPORT REQUIRED				INVOICE TO:	
Database Entry By			Date			PWSID				ADDRESS:	
		PAM		7/81//	7	San	nple Kit Se	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch 218/6/01

Telephone: (970) 226-5500

Facsimile: (970) 226-4946 PAGE \_\_\_\_ OF \_\_\_\_

SEGUSEONIYA CIEMINO	CLIENT:											
Sample No. S10- 209	SAMPLE Date	COLLECTION	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATIO	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature:  ANALYSES REQUESTED		
15274	7.27.17	15:00	A	MW-19			ww	1		Method 8260 (see back of COC) - SL		
			•							Metals - (see back of COC) SL		
									١	Inorganic Analysis (see back of COC) - SL		
										Sulfide		
				ture of samples as they ar	rive in the labo	ratory. W	ould you	like the ten	nperature	of samples recorded upon receipt by the laboratory? Please		
Editoria es a more de la agrafia		an Hu Yak		rature is not requested.	sted.							
RELINQUISHED B		7.27.17	Received	by	Date / Time	REQUES	TED CO	MPLETION	DATE	REPORT TO: PHONE:		
	0 1	16:20	Lat	Welte	16:20					FAX:		
Relinquished by		Date / Time	Received	by	Date / Time	1 tij	WW = wa	IX TYPE	- 7 ×	ADDRESS:		
					5 . / =:		L = Liquid	nking wate		CITY, STATE ZIP:		
Relinquished by		Date / Time	received	бу	Date / Time			SL = SD = ORT REQUI		INVOICE TO:		
Database Entry By		984818181818181	1500 P. (1000 P. (100			PWSID		OKI KISOO	d of the same of the best of	ADDRESS:		
ontabase cita y by			Date	7/28/.	17	Sar	nple Kit S	ent? Yes	/ No	CITY, STATE ZIP:		



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

245	6901
243	)

Telephone: (970) 226-5500		
Facsimile: (	PAGE	OF_

Client No. CLIEN	Т:		Stratus	s Comp	anies -	ACZ			Name: James Stewart
Sample No. SAMF	PLE COLLECTION Time	ON INFO Grab / Comp	CLIENT SAMPLE IDENTIFICATION			Matrix Type	QC Report	Total No. of Cont.	Signature:  ANALYSES REQUESTED
### 7.27.1	710:00	Cop	MO-	19		とと	\/	3	Phenois
		1				1	<u> </u>		Total Organic Carbon  Method 8270 (all normal compounds, including those below)
						<del> </del>			Benzyl Butyl Phthalate
									Bis(2-ethylhexyl) phthalate
									Di-n-butyl Phthalate
									Diethyl Phthalate
									Dimethyl Phthalate
									Di-n-octyl Phthalate
									1,4-Dioxane
									Benzoic Acid
	+								Bencyl alcohol
	-								2-Methylphenol
Compliance earnles r	nev require you	o report the te	mnerature of	camples as th	ev arrive in th	io laborato	Would ve	attille the fer	perature of sampless ecorded upon receipt by the
Leaving this field blar	nk implies that t	he incoming	temperature i	s not reques	ted.	(G)(a)voi(a)(v	, A College	Fig. 1	peratural samples second arraport accept by the
RELINQUISHED BY	DATE / TIME 7-27-17	Received by		Date / Time	REQUESTE	D COMPLI	TION DATE		REPORT TO: PHONE:
	14:10	OF	7/201	1410				<b>建设</b>	FAX:
Relinquished by		Received by	12917	Date / Time		MATE	IX TYPE	Alluny (Admin)	CLIENT:
Tromiquismod by	Date / Time	rederved by		Date / Time		WW =w	ste water -		ADDRESS:
						L = Liquid	100		CITY, STATE ZIP:
Relinquished by	Date / Time	Received by		Date / Time	-S=: 'A=	soil : di j	SL =	∹sludge. = Solid	INVOICE TO
							ORT REQUIR	ED	INVOICE TO:
Dalabase Entry By		Date			PWSID#		See William	V. V. V.	ADDRESS:
			7/25/	4/	Sa	ample Kit S	ent? Yes /	No	CITY, STATE ZIP:



## Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Clier	nt: Stratus Initials: JDM Date: 7/31/17	Time:	00	MST/MDT
	To be filled out by laboratory courier, if applicable:	Yes	No	NA
1	Were samples retrieved by a laboratory courier?	1		
2	Were samples on ice or in a refrigerated state upon retrieval?			
	Courier Initials: 1 Date: 7-28-17 Fime: 18-30			
	To be filled out by laboratory sample receiving:			
3	Shipping container/cooler intact?			
4	Chain of Custody (COC) present?	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
5	Sample bottles intact? *			
6	Samples on blue-ice?			
7	Samples on wet ice?	/		
8	Samples received within 4 hours of sampling?			
9	Record temperature of sample bottles within cooler with infra-red  Container #  Temp °C 4.80	thermometer		
	Temp C [1.8]	Yes	No	NA
10	Sample thawed and free of any ice? *			
11	COC complete, legible, signed and dated?			
12	Labels on bottles complete and legible? *			14
13	COC in agreement with sample bottle labels? *			
14	Proper container used for analyses requested? *	4		_
15	Samples requiring preservation preserved correctly? *	V		
16	Sufficient sample volume for analyses requested? *	N		_
17	Samples within holding times for analyses requested? *	V		
18	Samples requiring no headspace are free of headspace? *			
	(VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	_ < green pe	a,	> green pea
	* If no, document on Chain of Custody.			
Notes	: Put: uto fridge year arival			en .
				,



STEWART ENVIRONMENTAL CONSULTANTS, INC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Energy eggin

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St	ratus Compan	ies - Ste	wart	Labs			Name: SAMP	Steelar)
Sample No. S10= /98	SAMPLE Date	COLLECTION	INFO Grab / Comp	CLIENT SAMPLE	IDENTIFICATION	ON	Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES R	EQUESTED
	7-13-17	14:20	G	MW-2	0		WL	2	(0.	Method 8260 (see back	of coc)—stresomple
										Metals - (see back of Co	DC) SL
										Inorganic Analysis (see	back of COC) - SL
				. 4							
			e .								
Compliance sample check. Yes	es may require record and rep	you to report the	e tempera	iture of samples as they ar No, temperature not reque	rive in the labo	ratory. V	Vould you	like the ten	nperature	of samples recorded upon recei	ot by the laboratory? Please
		hat the incom	ing tempe	rature is not requested.							
RELINQUISHED BY	*	DATE TIME	Received	by	Date / Time 7/14/17	REQUE	STED CO	MPLETION	DATE	REPORT TO:	PHONE:
T	0 1	19:10	si	in which	10:00		201			CLIENT:	FAX:
Relinquished by		Date / Time	Received	by	Date / Time	Spring and their	MATRIX TYPE  WW = waste water			ADDRESS:	
						DW = drinking water L = Liquid				CITY, STATE ZIP:	
Relinquished by		Date / Time	Received	by	Date / Time	S = soil SL = sludge A = Air SD = Solid			Solid	INVOICE TO:	
						CDPHE REPORT REQUIRED  PWSID #			RED	ADDRESS:	
Database Entry By		MEGL	Date	7/17/17	7			ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Telephone: (970) 226-5500 Facsimile: ( PAGE \_\_\_\_ OF \_\_\_\_

ECLUSE ON Client No	CLIENT:			Stratus Comp	Name: Laues Steelert						
	SAMPLE Date	COLLECTION INFO Time Grab / Comp		CLIENT SAMPLE IDENTIFICATION		Matrix Type	QC Report Needed	Total No. of Cont.	Signature:	ANALYSES REQUESTED	
(C) [24]	7-13-17	14:20	GI	MW.20		ww		3	Method 8270 (	all normal compounds, including those below)	
			'						Total Orga	anic Carbon	
										utyl Phthalate	
									Bis(2-ethylhexyl) phthalate		
									Di-n-buty	l Phthalate	
									Diethyl Phthalate		
								Dimethyl Phthalate			
									Di-n-octyl Phthalate		
									1,4-Dioxa	ne	
									Benzoic Acid		
							Bencyl al	cohol			
									2-Methylp	henol	
Compliance samples may require you to report the temperature of samples as they arrive in the laboratory. Would you like the temperature of samples recorded upon receipt by the Leaving this field blank implies that the incoming temperature is not requested.											
RELINQUISHED BY		7.13.17 Received by		Date / Time	REQUESTED COMPLETION DATE				REPORT TO:	PHONE:	
	1		CIF	7/13/13/50					OL UTA IT	FAX:	
Relinguished	by		Received by	Date / Time		MATR	X TYPE		CLIENT:		
, tomique of		Bate / Time / teestrea by				WW = wa	ste water		ADDRESS:		
Relinquished by C		Date / Time Received by		Date / Time	0=0	L = Liquid	eı -		CITY, STATE ZI	P:	
				Date / Time	A = /	Air DPHE RERO	SL = SD = DRT REQUIRE	Solid .	INVOICE TO:		
Database Entry By		Date		PWSID#				ADDRESS:			
				Sample Kit Sent? Yes / No				CITY, STATE ZI	P:		



## Sample Receipt Checklist

STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

Clien	ESTRATUS Initials: JDW Date: 7/14/17	Time: / 0://	00	MST/MDT							
	To be filled out by laboratory courier, if applicable:	Yes	No	NA							
1	Were samples retrieved by a laboratory courier?	/									
2	Were samples on ice or in a refrigerated state upon retrieval?	1									
	Courier Initials: 1 Date: 7:13:17 Time: 19:10										
	To be filled out by laboratory sample receiving:										
3	Shipping container/cooler intact?										
4	Chain of Custody (COC) present?										
5	Sample bottles intact? *										
6	Samples on blue-ice?										
7	Samples on wet ice?	/									
8	Samples received within 4 hours of sampling?		/								
9	Record temperature of sample bottles within cooler with infra-red	thermomete	r.								
	Container #										
	Temp °C   4.80	Van									
40		Yes	No	NA							
10	Sample thawed and free of any ice? *										
11	COC complete, legible, signed and dated?										
12	Labels on bottles complete and legible? *			(8)							
13	COC in agreement with sample bottle labels? *										
14	Proper container used for analyses requested? *										
15	Samples requiring preservation preserved correctly? *		2								
16	Sufficient sample volume for analyses requested? *										
17	Samples within holding times for analyses requested? *										
18	Samples requiring no headspace are free of headspace? * (VOC, TVPH, BTEX, Ethanol, Radon) If no, size of bubble:	< green pe	ea.	> green pea							
	* If no, document on Chain of Custody.			<b>3</b> . con pos							
Notes	: MW20- recomple VOC	8260	1 - too	much							
	head space										



STEWART ENVIRONMENTAL CONSULTANTS, INC. 3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch: 24 5 6767

Telephone: (970) 226-5500

Facsimile: (970) 226-4946

SEC USE ONLY Client No.	CLIENT:		St		Name: Jan &	Fewart					
Sample No. \$10-267	SAMPLE Date	COLLECTION Time	INFO Grab / Comp	CLIENT SAMPLE	DENTIFICATION		Matrix Type	QC Report Needed	Total No. of Cont.	Signature: ANALYSES	REQUESTED
1/2 =	7.26.17 13:10 G		UW-20		ww	1/	\$3	Method 8260 (see back	of COC) - SL		
									Metals - (see back of C	<del>OC) S</del> L	
								Inorganic Analysis (see back of COC) - SI			
						1 50		30	Sulfide		
									1	Cn	
				ture of samples as they ar <b>No</b> , temperature not reque		ratory. W	ould you l	like the ten	nperature o	of samples recorded upon rece	ipt by the laboratory? Please
Leaving this field b	olank implies t	hat the incomi	ng tempe	rature is not requested.							
		7-2017	Received	by	Date / Time REQUE		QUESTED COMPLETION DATE		REPORT TO:	PHONE:	
		19:00	Leta alla		11:30					FAX:	
			Received by		Date / Time		MATRIX TYPE				
								WW = waste water DW = drinking water		ADDRESS:	
Relinquished by Da		Date / Time	Received by				L = Liquid S = soil		sludge	CITY, STATE ZIP:	
						COPHE REPORT REQUIRED					
Database Entry By			Date	iatė			#			ADDRESS:	
MAGE				7/23//2			nple Kit Se	ent? Yes	/ No	CITY, STATE ZIP:	



STEWART ENVIRONMENTAL CONSULTANTS, LLC. 2600 Canton Ct, Unit C, Fort Collins, CO 80525

#### Batch: 245 7180

Telephone: (970) 226-5500 Facsimile: (970) 226-4946

simile: (970) 226-4946 PAGE \_\_\_\_ OF \_\_\_

Client No.	CLIENT: Stewart Environmental									Print: Collec Starl +			
										Print ares Stewert			
Sample No.	Date	Time	Grab / Comp	Chlorine (ppm) if	SAMPLE IDENTIFI	CATION / NAM	E	Matrix Type	QC Report Needed	Total No. of Bottles	Signature:  Analyses Requested		
1624	8.23-17	15:00	G		Q,-HW-12			WW	7	3	8260B Including: 1,1-DCE; Freon-11; Freon-113; Trans 1,2-DCE; 1,1-DCA; Cis-1,2-DCE; Chloroform; 2-Butanone (MEK); 4-Isopropyltoluene; 1,1,1-TCA; Trichloroethelene (TCE); Toluene; tetrachloroethylene (Perc); tetrahydrofuran (THF); vinyl chloride; total xylenes; benzene Acetonitrile (Methyl Cyanide); Ethyl Methacrylate; 2-Pentanone, 4-Methanone		
											8270 Expanded List		
									Phenols, TKN, Mercury, Cyanide, Total Phosphorous. TOC				
											Anions, Metals, carb, bicarb, sulfide		
			-			· ·							
Notes:			<u></u>										
110(63.											REPORT TO: Trevor Mueller		
										PHONE: 970.226.5500 FAX:			
Relinquished by		Date / Time Received		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		REQU	UESTED COMPLETION DATE			E-MAIL: Lab@stewartenv.com			
Reimquished by Date / Tin			Received	by	Date / Time	ate / Time MATRIX TYPE WW = waste water				ADDRESS:			
Polineviched by						Ļ=	L = liquid W = water			2600 Canton Ct, Suite C CITY, STATE, ZIP:			
Relinquished by	Date / Time Received by Date / Time S = soil St = slud A = Air SD = Soil CDPHE REPORT REQUI				Solid	Fort Collins, CO 80525 INVOICE TO:							
Database Entry By	Date						QUIKED	ADDRESS:					
J DM										CITY, STATE ZIP:			